



PLASTIC-PART STRESS INDICATOR

Introducing the NEW plastic part stress indicator!
Now more economical and easier to carry!



Handy pocket-sized stress indicator is used to check stress patterns in molded plastic parts. Shows fracture marks and flaws not visible with the naked eye or many magnifiers.



Compact --3" x 3" when folded,
3" x 6" when open



Viewing a pair of safety glasses through the Stress Indicator.



Simple to Use

- Hold indicator up to light with molded part between the lenses.
- Stresses show up as darker coloring. Clear places are stress-free.

PART #	PRICE
MPSA1	\$33.00

© 2009 MOLDERS CHOICE, Inc.



24 Hour Service - 7 Days a week
1-800-809-4623
WebSite: www.molderschoice.com • Email: molders@molderschoice.com