


# Ball Check SCREW TIPS

**For Faster, More Positive, More Consistent Shutoff**



Recommended for:

- Large presses with screws 3.5" (90mm) or larger in diameter
- High-speed molding of Containers, Flower Pots, Buckets, Pails, etc
- General-Purpose Materials
- Free Flow Design with oversize pick-up holes



- Center Discharge design provides optimum Flow and Shutoff
- Premium H-13 Tool Steel Valve Body resists wear, deformation, and fatigue cracking.
- Stainless Steel Ball resists corrosion
- Ultra-hard D2 Tool Steel Ball Seat features lifetime warranty against wear and breakage.

## Also available in Longer Side-Discharge Design

Beware of inferior designs utilizing inexpensive weak steels. We use only Premium H13 for extended life in all molding applications

© 2009 MOLDERS CHOICE, Inc.



24 Hour Service - 7 Days a week  
**1-800-809-4623**  
WebSite: [www.molderschoice.com](http://www.molderschoice.com) • Email: [molders@molderschoice.com](mailto:molders@molderschoice.com)