


# PLASTIC-PART STRESS INDICATOR

**Introducing the NEW plastic part stress indicator!**  
Now more economical and easier to carry!



**Another Process  
Engineer Tool  
ONLY  
From Molders Choice**

Handy pocket-sized stress indicator is used to check stress patterns in molded plastic parts. Shows fracture marks and flaws not visible with the naked eye or many magnifiers.



**Compact** --3" x 3" when folded,  
3" x 6" when open



Viewing a pair of safety glasses through the Stress Indicator.



### Simple to Use

- Hold indicator up to light with molded part between the lenses.
- Stresses show up as darker coloring. Clear places are stress-free.

PART #	PRICE
<b>MPSA1</b>	<b>\$33.00</b>

© 2009 MOLDERS CHOICE, Inc.



**24 Hour Service - 7 Days a week**  
**1-800-809-4623**  
WebSite: [www.molderschoice.com](http://www.molderschoice.com) • Email: [molders@molderschoice.com](mailto:molders@molderschoice.com)